

# Payments NZ Device Register

Version Date: 6 June 2017



Manufacturer	Model	Hardware/Firmware Version	PCI Approval No	Approval Version/Class	Date of no new connection	PNZ Sunset Date
Castles Technology Co. Limited	MARS1000	Hardware Version: V1.01 Firmware Version: 0011	4-80020	PED 3.x	30/04/2020	TBD
Castles Technology Co. Limited	Vega3000	Hardware Version: VEGA3000-HW-v1.3.xxxx Firmware Version: xxxx-xxxx-xxxx-xxxx-0027	4-40195	PED 4.x	30/04/2023	TBD
Castles Technology Co. Limited	Vega 5000	Hardware Version: VEGA 5000_HW Version 1.0 Firmware Version: VEGA 5000_HW Version 1.0	4-60052	PED 2.x	30/04/2017	30/04/2020
Castles Technology Co. Limited	Vega3000	Hardware Version: V1.0 Firmware Version: VP013	4-40101	PED 3.x	30/04/2020	TBD
Castles Technology Co. Limited	Vega 5000S	Hardware Version: VEGA5000S-HW-1.0 Firmware Version: V1.1	4-40091	PED 3.x	30/04/2020	TBD
Cryptera A/S	Cryptera INT 7000	Hardware Version: xxx-3310-62xx R2 Firmware Version: 02.04.x.x	4-20190	UPT 1.x	30/04/2014	30/04/2018
Datec	Bluepad50	Hardware Version: 02.02.xx.xxbn Firmware Version: 414-0580 R2x	4-30109	PED 3.x	30/04/2020	TBD
Payment Express Limited	CHU200	Hardware Version: AB018X-BXX Firmware Version: 1.3.X.X	4-40197	PED 4.x	30/04/2023	TBD

Manufacturer	Model	Hardware/Firmware Version	PCI Approval No	Approval Version/Class	Date of no new connection	PNZ Sunset Date
Direct Payment Solutions	SCR200 & SKP200	Hardware Version: REV C Firmware Version: 1.2xx & 1.0xx	4-40077	PED 3.x	30/04/2020	TBD
Direct Payment Solutions	SKP200E	Hardware Version: SKP200E - Release C Firmware Version: DPSSKP200E v1.3xx	4-40127	PED 3.x	30/04/2020	TBD
Direct Payment Solutions	SCR200E	Hardware Version: SCR200E Release B Firmware Version: 1.3.x.x	4-40135	UPT 3.x	30/04/2020	TBD
Emerge Mobile	Edge Adapter	Hardware Version: 3.1 Firmware Version: 2.16	4-60170	PED 3.x	30/04/2020	TBD
Fujian Landi Commercial Equipment Co Ltd.	E550	Hardware Version: XX-03 Firmware Version: A9LIPP 01-04-04	4-40085	PED 3.x	30/04/2020	TBD
Gilbarco s.r.l.	Gilbarco SPOT M3c-2.1	Hardware Version: display: SPOT M3c Display Rev.B; GCM:M11697; keyboard: GVR SPOT Keypad Unit 2.0 Rev.B; card reader: GVR HO-MR Reader (motorized) or GVR NS-MR Reader (motorized), MagTek HCR2 Rev 14.x, 16.x Firmware Version: OS 01.03, MagTek HCR2: E0x, H0x	4-20182	PED 2.x	30/04/2017	30/04/2020
Ingenico	iUR255, iUR255P	Hardware Version: iUR2xx-01Txxxxxx, iUR2xx-11Txxxxx Firmware Version: 820168 v01.xx	820168 v01.xx	PED 4.x	30/04/2023	TBD
Ingenico	iUI120	Hardware Version: iUI1xx-01Txxxxx Firmware Version: 820167 V11.xx	iUI120	PED 4.x	30/04/2023	TBD

Manufacturer	Model	Hardware/Firmware Version	PCI Approval No	Approval Version/Class	Date of no new connection	PNZ Sunset Date
Ingenico	i3010	Hardware Version: i301001P01 Firmware Version: 424845A	4-30020	PED 1.x	30/04/2014	30/04/2018
Ingenico	i3070	Hardware Version: i3070MPO4 Firmware Version: UniCapt32.2.x.y, UniCapt 32 3.x.y	4-20005C	PED 1.x	30/04/2014	30/04/2018
Ingenico	i5100	Hardware Version: i5100MH10,i5100MP10, i5100omH12 Firmware Version: UniCapt32.2.x.y, UniCapt 32 3.x.y SSA 02.XX	4-20033	PED 1.x	30/04/2014	30/04/2018
Ingenico	i5310	Hardware Version: i5310MH10,i5310MH12 Firmware Version: UniCapt32.2.x.y, UniCapt 32 3.x.y	4-20033	PED 1.x	30/04/2014	30/04/2018
Ingenico	i6510	Hardware Version: i65AAMH01,i65AAMH02, i65ABMH02, Firmware Version: OS 2.x.x, UniCapt32 2.x.y,UniCapt32 3.x.y	4-40006	PED 1.x	30/04/2014	30/04/2018
Ingenico	i7780	Hardware Version: i7780MH10,i7780MH12 Firmware Version: UniCapt32 2.x.y, UniCapt 32 3.x.y	4-20038	PED 1.x	30/04/2014	30/04/2018
Ingenico	i7910	Hardware Version: i7780MH10,i7780MH12, Firmware Version: UniCapt32 2.x.y, UniCapt 32 3.x.y	4-20038	PED 1.x	30/04/2014	30/04/2018
Ingenico	i9500	Hardware Version: i9500 K301 (PIN PAD) i9500 R301 (Reader) Firmware Version: UniCapt 32 3.x.y	4-30035	PED 2.x	30/04/2017	30/04/2020

Manufacturer	Model	Hardware/Firmware Version	PCI Approval No	Approval Version/Class	Date of no new connection	PNZ Sunset Date
Ingenico	ICT2xx	Hardware Version: ICT2xx-01 Txxxxx Firmware Version: 820305 V01.xx	4-20106	PED 2.x	30/04/2017	30/04/2020
Ingenico	IPP2xx	Hardware Version: IPP2xx-01 Txxxxx Firmware Version: 820514 V01.xx	4-20148	PED 2.x	30/04/2017	30/04/2020
Ingenico	IPP3xx	Hardware Version: IPP3xx-01 Txxxxx Firmware Version: 820305 V01.xx	4-20142	PED 2.x	30/04/2017	30/04/2020
Ingenico	IWL2xx	Hardware Version: IWL2xx-01 Txxxxx Firmware Version: 820305 V01.xx	4-20161	PED 2.x	30/04/2017	30/04/2020
Ingenico	iSMP	Hardware Version: iMP3xx-01Txxxxx Firmware Version: 820305 V01.xx	4-20175	PED 2.x	30/04/2017	30/04/2020
Ingenico	IWL2xx	Hardware Version: IWL2xx-11Txxxxx Firmware Version: 820518V01.xx, 820365V02.xx, 820528v02.xx (SRED)	4-20179	PED 3.x	30/04/2020	TBD
Ingenico	iSMP or iMP3xx	Hardware Version: iMP3xx-01Txxxxx Firmware Version: 820305V01.xx, 820365V02.xx, 820528v02.xx	4-20183	PED 3.x	30/04/2020	TBD
Ingenico	ICT2xx	Hardware Version: ICT2xx-11Txxxxx Firmware Version: 820305V02.xx,820365V02.xx,820528v02.xx	4-20196	PED 3.x	30/04/2020	TBD
Ingenico	IPP2xx	Hardware Version: IPP2xx-01Txxxxx FirmwareVersion:820514V02.xx,820365V02. xx	4-20199	PED 3.x	30/04/2020	TBD

Manufacturer	Model	Hardware/Firmware Version	PCI Approval No	Approval Version/Class	Date of no new connection	PNZ Sunset Date
Ingenico	IPP3x	Hardware Version:IPP3xx-11Txxxxx Firmware Version:820305V02.xx,820365V02.xx,820528v02.xx	4-20184	PED 3.x	30/04/2020	TBD
Ingenico	IPP310	Hardware Version: IPP3xx-11Txxxxx Firmware Version: 820305 V02.xx, 820365V02.xx, 820528V02.xx	4-20184	PED 3.x	30/04/2020	TBD
Ingenico	iCMP	Hardware Version: iCMxxx-01Txxxxx, iCMxxx-11Txxxxx, iCMxxx-21Txxxxx, iCMxxx-31Txxxxx Firmware Version: 820305V01.xx, 820365V02.xx (schemes), 820528V02.xx (SRED), 820539V01.xx (SRED)	4-20235	PED 3.x	30/04/2020	TBD
Ingenico	IWL2xx	Hardware Version: IWL2xx-01Txxxxx Firmware Version: 820305V01.xx, 820365V02.xx, 820528v02.xx (SRED)	4-20181	PED 3.x	30/04/2020	TBD
Ingenico	IUP2XX	Hardware Version: IUP2XX-01Txxxxx Firmware Version: 820305 V01.xx	4-30075	PED 3.x	30/04/2020	TBD
Ingenico	iUR250, iUR250P	Hardware Version: iUR2xx-01Txxxxx, iUR2xx-11Txxxxx Firmware Version: 820514V01.xx	4-30083	UPT 3.x	30/04/2020	TBD
Invenco	G6OPT	Hardware Version: 01.00.xx, 1.06.xx, 1.07.xx Firmware Version: 01.00.xx, 2.01, 2.06.16, 02.10.xx	4-40068	PED 3.x	30/04/2020	TBD
Keycorp Ltd	K23	Hardware Version: 3.x Firmware Version: PCI API V1.04	4-50001	PED 1.x	30/04/2014	30/04/2018

Manufacturer	Model	Hardware/Firmware Version	PCI Approval No	Approval Version/Class	Date of no new connection	PNZ Sunset Date
Keycorp Ltd	K23P-5xx	Hardware Version: 3.x Firmware Version: PCI API V01.04	4-50001	PED 1.x	30/04/2014	30/04/2018
Miura System Ltd	Shuttle	Hardware Version: M010-PRODxx-V1-x Firmware Version: M000-OS-V7-x	4-30084	PED 3.x	30/04/2020	TBD
Neo ICP Korea	K1200	Hardware Version: EPP, HW#050002 Firmware Version: FU 092015	4-40039	PED 1.x	30/04/2014	30/04/2018
PAX Technology	S920 S920L	Hardware Version: S920-xxx-xx4-0xxx, S920-xxx-xx4-1xxx Firmware Version: Prolin OS: 14.00.xx Prolin Boot: 2.0.x	4-30159	PED 4.x	30/04/2023	TBD
PAX Technology	S900	Hardware Version: Firmware Version:	4-30204	PED 4.x	30/04/2023	TBD
PAX Technology	S800	Hardware Version: S800-xxx-3x4-0xxx Firmware Version: 14.01.xx xxxx	4-30225	PED 4.x	30/04/2023	TBD
PAX Technology	S300	Hardware Version: S300-xxx-3x4-0xxx Firmware Version: 14.01.xx xxxx	4-30224	PED 4.x	30/04/2023	TBD
PAX Technology	D200	Hardware Version: D200-000-xx3-0xxx Firmware Version: 1.5	4-60147	PED 3.x	30/04/2020	TBD
PAX Technology	D210	Hardware Version: D210-000-xx3-0xxx Firmware Version: D210 PED 1.2	4-60148	PED 3.x	30/04/2020	TBD
PAX Technology	D210	Hardware Version: D210-xxx-xx4-0xxx Firmware Version: 4.00.xx	4-40157	PED 4.x	30/04/2023	TBD

Manufacturer	Model	Hardware/Firmware Version	PCI Approval No	Approval Version/Class	Date of no new connection	PNZ Sunset Date
PAX Technology	S80	Hardware Version: S80xx-102 Firmware Version : PEDV1.	4-10041	PED 1.x	30/04/2014	30/04/2018
PAX Technology	S80	Hardware Version: S80-XXX-201 Firmware Version: S80 PED 2.1	4-60068	PED 2.x	30/04/2017	30/04/2020
PAX Technology	S80	Hardware Version: S80-MGL-xx3-0xxx, S80-MCL-xx3-0xxx, S80-MTL-xx3-0xxx, S80-MWL-xx3-0xxx, S80-MEL-xx3-0xxx, S80-MOL-xx3-0xxx, S80-MGW-xx3-0xxx, S80-MCW-xx3-0xxx, S80-MTW-xx3-0xxx, S80-MWW-xx3-0xxx, S80-MEW-xx3-0xxx, S80-MOW-xx3-0xxx, S80-MGA-xx3-0xxx, S80-MCA-xx3-0xxx, S80-MTA-xx3-0xxx, S80-MWA-xx3-0xxx, S80-MEA-xx3-0xxx, S80-MOA-xx3-0xxx, S80-MG0-xx3-0xxx, S80-MC0-xx3-0xxx, S80-MT0-xx3-0xxx, S80-MW0-xx3-0xxx, S80-ME0-xx3-0xxx, S80-M00-xx3-0xxx, S80-0GL-xx3-0xxx, S80-0CL-xx3-0xxx, S80-0TL-xx3-0xxx, S80-0WL-xx3-0xxx, S80-0EL-xx3-0xxx, S80-00L-xx3-0xxx, S80-0GW-xx3-0xxx, S80-0CW-xx3-0xxx, S80-0TW-xx3-0xxx, S80-0WW-xx3-0xxx, S80-0EW-xx3-0xxx, S80-00W-xx3-0xxx, , S80-0GA-xx3-0xxx, S80-0CA-xx3-0xxx, S80-0TA-xx3-0xxx, S80-0WA-xx3-0xxx, S80-0EA-xx3-0xxx, S80-00A-xx3-0xxx, S80-0G0-xx3-0xxx, S80-0C0-xx3-0xxx, S80-0T0-xx3-0xxx, S80-0W0-xx3-0xxx, S80-0E0-xx3-0xxx, S80-000-xx3-0xxx Firmware Version: S80 PED 3.1	4-40083	PED 3.x	30/04/2020	TBD
PAX Technology	S90	Hardware Version: S90-X-101 Firmware Version: PED V1.0	4-60010	PED 1.x	30/04/2014	30/04/2018

Manufacturer	Model	Hardware/Firmware Version	PCI Approval No	Approval Version/Class	Date of no new connection	PNZ Sunset Date
PAX Technology	S90	Hardware Version: S90-xxx-201 Firmware Version: S90 PED 2.1	4-60067	PED 2.x	30/04/2017	30/04/2020
PAX Technology	S90	Hardware Version: S90-MGW-xx3-0xxx, S90-MCW-xx3-0xxx, S90-MTW-xx3-0xxx, S90-MWW-xx3-0xxx, S90-MEW-xx3-0xxx, S90-MOW-xx3-0xxx, S90-MG0-xx3-0xxx, S90-MC0-xx3-0xxx, S90-MT0-xx3-0xxx, S90-MW0-xx3-0xxx, S90-ME0-xx3-0xxx, S90-M00-xx3-0xxx, , S90-0GW-xx3-0xxx, S90-0CW-xx3-0xxx, S90-0TW-xx3-0xxx, S90-0WW-xx3-0xxx, S90-0EW-xx3-0xxx, S90-00W-xx3-0xxx, , S90-0G0-xx3-0xxx, S90-0C0-xx3-0xxx, S90-0T0-xx3-0xxx, S90-0W0-xx3-0xxx, S90-0E0-xx3-0xxx, S90-000-xx3-0xxx Firmware Version: S90 PED 3.1	4-40082	PED 3.x	30/04/2020	TBD
PAX Technology	SP30	Hardware Version: SP30xx-102 Firmware Version: PED V1.	4-60006	PED 1.x	30/04/2014	30/04/2018
PAX Technology	SP30	Hardware Version: SP30-xxx-201 Firmware Version: SP30 PED 2.1	4-60049	PED 2.x	30/04/2017	30/04/2020
PAX	S300	Hardware Version: S300-abc-dx3-0xxx Firmware Version: Prolin 21.3xx.xxx.xxx.1xx (boot 1.0.0 PED 001)	4-40094	PED 3.x	30/04/2020	TBD
PAX	S800	Hardware Version: S800-abc-dx3-0xxx Firmware Version: Prolin 21.3xx.xxx.xxx.1xx (boot 1.0.0 PED 001) (SRED)	4-40088	PED 3.x	30/04/2020	TBD



Manufacturer	Model	Hardware/Firmware Version	PCI Approval No	Approval Version/Class	Date of no new connection	PNZ Sunset Date
PAX	S900	Hardware Version: S900-abc-dx3-0xxx Firmware Version: Prolin 21.3xx.xxx.xxx.1xx (boot 1.0.0 PED 001)	4-40089	PED 3.x	30/04/2020	TBD
Point of Pay Ltd	Point of Pay (PoP)	Hardware Version: PoP-039-01-PoP Firmware Version: 1.25 PCI-PED	4-40015	PED 1.x	30/04/2014	30/04/2018
Provenco Cadmus	G50PT	Hardware Version: 3.9.0 Firmware Version: 6.0661,9.0.0141	4-40007	PED 1.x	30/04/2014	30/04/2018
Quest Payment Systems	QT720	Hardware Version: 800-0025-0X, 800-0025-1X Firmware Version: 04.XX.YY	4-300043	PED 2.x	30/04/2017	30/04/2020
Quest Payments Systems	H50	Hardware Version: 1.01 Firmware Version: 1.1.2	4-10005	PED 1.x	30/04/2014	30/04/2018
Quest Payments Systems	DUO	Hardware Version: 800-888x.0x Firmware Version: 04.XX.YY	4-30058	PED 2.x	30/04/2017	30/04/2020
Quest Payments Systems	MT330	Hardware Version: 800-004X-0Y Firmware Version: 05.11.01	4-30124	PED 3.x	30/04/2020	TBD
Quest Payments Systems	UT430	Hardware Version: 800-0050-0X Firmware Version: 05.xx.yy	4-30133	PED 3.x	30/04/2020	TBD
Quest Payments Systems	UT430n	Hardware Version: 800-0051-0X Firmware Version: 05.xx.yy	4-30138	PED 3.x	30/04/2020	TBD
Quest Payments Systems	QT720	Hardware Version: 800-0025-2X Firmware Version: 06.xx.yy	4-30208	PED 4.x	30/04/2023	TBD

Manufacturer	Model	Hardware/Firmware Version	PCI Approval No	Approval Version/Class	Date of no new connection	PNZ Sunset Date
Spectra Technologies	SP530	Hardware Version: SP530-xx-xxxx-xxxx1x-xx Firmware Version: Firmware Version: BLOADER V1.1; SYSTEM v1.1; SAM_DRV V1.1; EMVDLL V5.1; PEDDLL V1.1; EMVCLDLL V1.0	4-40166	PED 4.x	30/04/2023	TBD
Spectra Technologies	T1000	Hardware Version: TTxxxx-xxxxx-xxxx1-xx-xx Firmware Version: PEDDLL V3.0, HSM V1.3	4-40073	PED 3.x	30/04/2020	TBD
Spectra Technologies	Creon	Hardware Version: Cxxxx-xxxxxx-x Firmware Version: 1.0,1.1,1.2	4-30004	PED 1.x	30/04/2014	30/04/2018
Spectra Technologies	PR608	Hardware Version: P1.0 Firmware Version: Sam_Driver Ver 1.0	4-40030	PED 1.x	30/04/2014	30/04/2018
Spectra Technologies	PP300	Hardware Version: LCPP-xxxx1x-xx & LRCPP-xxxx1x-xx Firmware Version: 1.1	4-30018	PED 1.x	30/04/2014	30/04/2018
Spectra Technologies	PP300	Hardware Version: Ver 1 Firmware Version: PP300 PED v2.0	4-40095	PED 3.x	30/04/2020	TBD
Symlink	AS320	Hardware Version: AS-PED-01-HW-XX-V1.01 Firmware Version: AS-PED-01-FW-V1.01	4-40038	PED 2.x	30/04/2017	30/04/2020
Uniform Industrial Corp	PP790SE	Hardware Version: PP790SE-xxxxxxxxx, PP790SE-xxxxxxxxx A, PP790SE-xxxxxxxxxB Firmware Version: 792SC411 (System Core),	4-10039	PED 1.x	30/04/2014	30/04/2018
Uniform Industrial Corp	PP791	Hardware Version: PP791-xxxxxxxxxxxx Firmware Version: uBoot v101, Kernel v101,	4-10165	PED 3.x	30/04/2020	TBD

Manufacturer	Model	Hardware/Firmware Version	PCI Approval No	Approval Version/Class	Date of no new connection	PNZ Sunset Date
		SysMgr v101, SysMgr v201				
Uniform Industrial Corp	TS890	Hardware Version: TS890-xxxxxxxAxxx, TS890-xxxxxxxBxxx  Firmware Version: IPP s100, RFS0010, RFS0020	4-10113	PED 3.x	30/04/2020	TBD
VeriFone	UX100	Hardware Version: M159-10x-xxx-xxx Firmware Version: FWUX 01.05.xx, FWUX 01.06.xx	4-20299	PED 4.x	30/04/2023	TBD
VeriFone	UX301	Hardware Version: M159-301-xxx-xxx Firmware Version: Vault 12.x.x, OP 7.x.x, SRED 5.x.x, AppManager 6.x.x	4-20299	PED 4.x	30/04/2023	TBD
VeriFone	V200c / V200c PLUS	Hardware Version: H420-07-03-XXX-X0-A2 (V200c),H420-07-33-XXX-X1-A2 (V200c Plus) Firmware Version: Vault: 1.x.x, AppM: 10.x.x, VFSRED: 5.x.x, VFOP: 1.x.x, Vault: 5.x.x`	4-30182	PED 4.x	30/04/2023	TBD
VeriFone	P400/P400 Plus	H435-07-02-XX0-X0-A0 (P400) H435-07-32- XX0-X0-A0 (P400 Plus)  Vault: 2.x.x, AppM: 7.x.x, VFSRED: 5.x.x, VFOPI: 1.x.x	4-10191	PED 4.x	30/04/2023	TBD
VeriFone	X10 (Carbon)	SUB179-xx1-01-A  Vault: 2.x.x; AppM: 7.x.x; VFSRED: 5.x.x; VFOP: 1.x.x	4-10209	PED 4.x	30/04/2023	TBD
VeriFone	UX300	Hardware Version: M159-30x-xxx-xxx / M159-30x-xxx-xxx-B  Firmware Version: Vault 12.x.x SRED 5.x.x AppManager 6.x.x	4-20261	PED 3.x	30/04/2020	TBD

Manufacturer	Model	Hardware/Firmware Version	PCI Approval No	Approval Version/Class	Date of no new connection	PNZ Sunset Date
VeriFone	UX301	Hardware Version: M159-301-xxx-xxx Firmware Version: Vault 12.x.x SRED 5.x.x AppManager 6.x.x	4-20261	PED 3.x	30/04/2020	TBD
VeriFone	UX400	Hardware Version: M159-40x-xxx-xxx Firmware Version: AppManager 4.x.x, Vault 4.x.x, 7.x.x, 7A.x.x OP 4.x.x, 5.x.x, 7.x.x SRED 4.x.x AppManager 4A.x.x	4-20261	PED 3.x	30/04/2020	TBD
VeriFone	UX401	Hardware Version: M159-401-xxx-xxx Firmware Version: AppManager 4.x.x, Vault 4.x.x, 7.x.x, 7A.x.x OP 4.x.x, 5.x.x, 7.x.x SRED 4.x.x AppManager 4A.x.x		PED 3.x	30/04/2020	TBD
VeriFone	UX100	Hardware Version: M159-10x-xxx-xxx Firmware Version: FWUX 01.00.xx FWUX 01.03.xx	4-20259	PED 3.x	30/04/2020	TBD
VeriFone	Mx830	Hardware Version: M090-XOX-XX-R Firmware Version: MX0003US,	4-10025	PED 1.x	30/04/2014	30/04/2018
VeriFone	Mx850	Hardware Version: M090-X0X-XX-R Firmware Version: MX0003US,	4-10025	PED 1.x	30/04/2014	30/04/2018
VeriFone	Mx870	Hardware Version: M090-10X-XX-R Firmware Version: MX0006US	4-10003	PED 1.x	30/04/2014	30/04/2018
VeriFone	Nurit 8210SPCxxx	Hardware Version: 8210xxxxxyxx or 8210-xx-Mxx-xxx-yxx y=C,D or E Firmware Version: NOS7-SPED-FW-03.10.xx,-03.11.xx,03.12xx,03.13xx	4-20022	PED 1.x	30/04/2014	30/04/2018

Manufacturer	Model	Hardware/Firmware Version	PCI Approval No	Approval Version/Class	Date of no new connection	PNZ Sunset Date
VeriFone	OP312, OP313	Hardware Version: OP3122000x123xxxx/09313000x123xxxx Firmware Version: 2.4	4-20003	PED 1.x	30/04/2014	30/04/2018
VeriFone	SC5000 PIN PAD	Hardware Version: M108-xxx-Ax-yyy, M108-xxx-Bx-yyy, M108-xxx-Cx-yyy, M108-xxz-xx-yyy Firmware Version: ROM OS 4.01, ROM OS 5.10	4-20013	PED 1.x	30/04/2014	30/04/2018
VeriFone	Vx510	Hardware Version: M251-xxx-3x-xxx Firmware Version: QA0010A0	4-30014	PED 1.x	30/04/2014	30/04/2018
VeriFone	Vx520	Hardware Version: M252-6xxx-xx-xxn-2, M252-7xx-xx-xxx-2, M252-8xx-xx-xxx-2 Firmware Version: QT52EL20M	4-30050	PED 2.x	30/04/2017	30/04/2020
VeriFone	Vx520	Hardware Version:M252-XXX-XX-XXX-XXX-3 Firmware Version:QT52E20M	4-30052	PED 3.x	30/04/2020	TBD
VeriFone	Vx570	Hardware Version: M257-xxx-xx-xxx Firmware Version: QC0006A5	4-10004	PED 1.x	30/04/2014	30/04/2018
VeriFone	Vx610	Hardware Version: M256-xxx-3x-xxx Firmware Version: QB0111A0, QB00111A1, QB0111A2	4-30015	PED 1.x	30/04/2014	30/04/2018
VeriFone	Vx670	Hardware Version: M257-xxx-xx-xxx Firmware Version: QD0007A1	4-40005	PED 1.x	30/04/2014	30/04/2018
VeriFone	Vx675	Hardware Version:M265-xxx-xx-xxx-3 Firmware Version:QT650101	4-10116	PED 3.x	30/04/2020	TBD

Manufacturer	Model	Hardware/Firmware Version	PCI Approval No	Approval Version/Class	Date of no new connection	PNZ Sunset Date
VeriFone	Vx680	Hardware Version: M268-7xx-xx-xxn-o Firmware Version: QT68X20T	4-20146	PED 2.x	30/04/2017	30/04/2020
VeriFone	Vx680	Hardware Version: M268-7XX-XX-XXN-3 Firmware Version: QT68001D	4-30053	PED 3.x	30/04/2020	TBD
VeriFone	Vx700	Hardware Version: M270-xxx-xx-xxx Firmware Version: QH0011A1	4-20096	PED 1.x	30/04/2014	30/04/2018
VeriFone	Vx805	Hardware Version: M280-70X-XX-XXX-3 Firmware Version: QT850017	4-10106	PED 3.x	30/04/2020	TBD
VeriFone	Vx810	Hardware Version: M281-xxx-xx-xxx Firmware Version: QG0009A0	4-30019	PED 1.x	30/04/2014	30/04/2018
VeriFone	Vx820	Hardware Version: M282-X0X-XX-XXX-R-3 Firmware Version: QG0009A0	4-40053	PED 2.x	30/04/2017	30/04/2020
VeriFone	Vx820	Hardware Version: M282-X0X-XX-XXX-3 and M282-XXX-XX-XXX-3 Firmware Version: QT8200001	4-40054	PED 3.x	30/04/2020	TBD
VeriFone	e335	Hardware Version: M087-321-x0-xxx, M087-322-x0-xxx Firmware Version: QTE30102, QTE30104, QTE30201	4-30114	PED 3.x	30/04/2020	TBD
VeriFone	e315	Hardware Version: M087-311-x0-xxx, M087-312-x0-xxx Firmware Version: QTE30102, QTE30104, QTE30201	4-30111	PED 3.x	30/04/2020	TBD

Manufacturer	Model	Hardware/Firmware Version	PCI Approval No	Approval Version/Class	Date of no new connection	PNZ Sunset Date
VeriFone	e105	Hardware Version: M087-412-XX-XXX Firmware Version: 2.0.0	4-310143	UPT 3.x	30/04/2020	TBD
VeriFone	e355	Hardware Version: M087-351-X1-XXX Firmware Version: QTE35301.xxxxxxxx, OP: 1.x.x.x, QTE50301.xxxxxxxx	4-30168	PED 4.x	30/04/2023	TBD
VeriFone	VX 690	Hardware Version: M260-x1x-xx-xxx-3 Firmware Version: QT690260	4-30128	PED 3.x	30/04/2020	TBD